


FIG. 2

1:COMMUNICATION SYSTEM



COMMUNICATION STATE MONITOR	E MONITOR		
		VIDEO COMMUNIC	VIDEO COMMUNICATIONS: 2.4 GHz/11g
Ali COMMUNICATIONS NOT AVAILABLE	INTERNET COMMUNICATION AVAILABLE	INTERNET & VIDEO COMMUNICATIONS AVAILABLE	ALL COMMUNICATIONS ARE IN GOOD CONDITIONS
2.4GHz/11g		PHYSICAL RATE BEING RAISED TO 36 Mbps	
5GHz/11a			
PLEASE CHANGE DIRECTION OF ANTENNA OR MOVE MAIN BODY CLOSER TO VIDEO TRANSMITTER.	TION OF ANTENNA LOSER TO VIDEO TRA	ANSMITTER.	

FIG. 4





FIG. 5









FIG. 7







FIG. 8







FIG. 9






FIG. 11




FIG. 12





FIG. 13






FIG. 16

